

Date: October 06, 2026

To National Stock Exchange of India Ltd Exchange Plaza, 5th Floor, C-1, Block G, Bandra Kurla Complex, Bandra (E), Mumbai 400051 Symbol: REGAAL	To BSE Limited 1 st Floor, Phiroze Jeejeebhoy Towers Dalal Street Mumbai – 400001 Scrip Code: 544485
---	---

Subject: Disclosure under Regulation 30 read with Para B of Part A of Schedule III of SEBI (Listing Obligations and Disclosure Requirements) Regulations 2015 - Restoration of Operations

Dear Sir/ Madam,

In continuation to our earlier disclosure dated 10th September, 2026 and 1st October, 2026 made pursuant to Regulation 30 read with Schedule III of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 (“Listing Regulations”), regarding disruption of operations due to the damage detected in the rotor and fan of one of the Company’s turbines (“The Turbine”) having capacity of 10 MW at the Company’s newly commissioned manufacturing facility of 825 TPD located at Bhatgaon, Galgalia Check Post, Thakurganj Block, District-Kishanganj, Bihar – 855106, we wish to inform you that the repair and recommissioning activities of the Turbine have been successfully completed and operations have been restored.

The requisite details as per the SEBI Master Circular No. HO/49/14/14(7)2025-CFD-POD2/I/3762/2026 dated January 30, 2026 is enclosed as **Annexure A**.

This disclosure shall also be made available on the website of the Company at <https://regaalresources.com/>.

Kindly take the same on record.

Yours faithfully

For Regaal Resources Limited

TINKU
KUMAR
GUPTA

Digitally signed by
TINKU KUMAR
GUPTA
Date: 2026.10.06
19:33:36 +05'30'

Tinku Kumar Gupta

Company Secretary and Compliance Officer

ANNEXURE – A

Particulars	Disclosures
Insurance amount claimed and realized by the listed entity for the loss/damage;	The Company has claimed Rs 90 lakhs plus actual freight for the loss/damage incurred. Currently, the realisation of the claim is under process with the Insurance Company.
The actual amount of damage caused due to natural calamity or other force majeure events disruption;	The cost to repair the rotor and fan of The Turbine is INR 90 lakhs plus actual freight.
Details of steps taken to restore normalcy and the impact of the disruption natural calamity/other force majeure events on production or service, financials of the entity.	On 26th August, 2026, damage was detected in the rotor and fan of The Turbine. The Company undertook necessary inspection, assessment and repair measures in consultation with technical experts and the equipment/service providers. The damaged components were duly repaired/replaced, followed by testing, re-commissioning and performance checks of the Turbine. Accordingly, operations at the affected manufacturing facility have been restored and the Company is taking necessary measures to ensure stable and normal operations of the facility. During the period in which the Turbine was under repair, the additional capacity of 10 MW associated with the Turbine was not operational, resulting in a temporary impact on the incremental production capacity of the newly commissioned manufacturing facility.

	However, the Company had sufficient stock to service its existing and ongoing customer orders, and accordingly, such orders remained unaffected during the repair period. The cost to repair the rotor and fan of The Turbine is INR 90 lakhs plus actual freight.
--	--

For Regaal Resources Limited

TINKU
KUMAR
GUPTA

Digitally signed by
TINKU KUMAR GUPTA
Date: 2026.10.06
19:34:12 +05'30'

Tinku Kumar Gupta
Company Secretary & Compliance Officer