ऑयल इंडिया लिमिटेड
Oil India Limited
भारत सरकार के अधीन
एक महारत्न सीपीएसई
A Maharatna CPSE under
Government of India

निगमित कार्यालय /Corporate Office
यूनिट नं./ Unit No. K-400, 500, 600, टावर-के/ Tower-K,
वर्ल्ड ट्रेड सेन्टर / World Trade Centre
नौरोजी नगर / Nauroji Nagar, नई दिल्ली / New Delhi-110029
फोन /Phone: +91-011-26181010
ई-मेल/E-mail: oilindia@oilindia.in

Ref. No. OIL/SEC/32-33/NSE-BSE
Dated: 06.11.2026

National Stock Exchange of India Limited Exchange Plaza, Plot No. C/1, G Block, Bandra Kurla Complex, Bandra (E), Mumbai - 400 051 **Symbol**: OIL	**BSE Limited** Department of Corporate Service Phiroze Jeejeebhoy Towers Dalal Street Mumbai - 400 001 **Security Code**: 533106

Sub: **Press Release – Reported Fire incident at Indirect Bath Heater (IDBH) at Intermediate Tank Farm (ITF)-Tengakhat on 6th November, 2026**

Ref : **Regulation 30 of the SEBI (LODR) Regulations, 2015**

Sir / Madam,

Pursuant to Regulation 30 of the SEBI (LODR) Regulations, 2015, Press Release dated 06.11.2026 on the captioned subject, is submitted herewith for your information & records please.

Thanking you,

Yours faithfully,
For Oil India Limited

Ajaya Kumar Sahoo
Digitally signed by Ajaya Kumar Sahoo
Date: 2026.11.06 16:51:12 +05'30'

A.K. Sahoo
Company Secretary &
Compliance Officer

Encl: As above

Oil India Limited

Press Release

PRESS STATEMENT

Reported Fire incident at Indirect Bath Heater (IDBH) at Intermediate Tank Farm (ITF)-Tengakhat on 6th November, 2026

Duliajan, 6 November 2026: At about 9:05 AM a fire incident took place at IDBH during maintenance activities at ITF-Tengakhat near Duliajan of Oil India Limited at Dibrugarh District, Assam. The incident occurred at indirect bath heater area which was taken for maintenance and was in isolation since 4th November 2026.

Seven persons of the O&M Contractor sustained burn injuries in the fire incident. While six persons were rescued and taken for medical treatment, one person succumbed to the injuries at the incident site. Of the six injured persons, five have been taken to Assam Medical College and Hospital (AMCH), Dibrugarh, Assam, while one has been taken to OIL Hospital, Duliajan. Medical treatment is being provided to all the injured persons.

Fire fighting started through fixed firefighting system of the installation and OIL's Fire service department immediately mobilised fire tender & Dry Chemical Powder (DCP) tender to douse the fire, and the fire was extinguished at 12:30 PM and situation is under control. Total eleven fire tenders were deployed at site.

An internal inquiry committee has been constituted to investigate the incident for immediate and underlying cause leading to the incident, damage assessment and suggest proactive measures to avoid such incidents in future.

OIL express its deepest condolence to the bereaved family.

****




