



10th June 2026
IOLCP/CGC/2026

National Stock Exchange of India Ltd.
Exchange Plaza, Plot no. C/1, G Block,
Bandra-Kurla Complex, Bandra (E), Mumbai – 400051
Security Symbol: **IOLCP**

BSE Limited
Phiroze Jeejeebhoy Towers,
Dalal Street, Mumbai- 400 001
Security Code: **524164**

Sub: Disclosure under Regulation 30 of the Securities and Exchange Board of India (Listing Obligations and Disclosure Requirements) Regulations, 2015

Dear Sir/Madam,

Pursuant to Regulation 30 read with Para B of Part A of Schedule III of the Securities and Exchange Board of India (Listing Obligations and Disclosure Requirements) Regulations, 2015 ("SEBI LODR Regulations"), we would like to inform you that a minor fire incident occurred at approximately 9:50 p.m. on 9th June 2026, in Unit-9B, the Company's Minoxidil manufacturing unit

No injuries were reported to any employee or other personnel, and no significant damage to plant/property was caused as a result of the incident. The incident was promptly attended to and brought under control by the Company's site emergency response team in accordance with the established Onsite Emergency Management Plan. The incident was confined to Unit-9B and did not affect the operations of the Company's other manufacturing units/plants, all of which continue to operate normally.

As a precautionary measure and to facilitate the necessary inspection, assessment, and restoration activities, operations at Unit-9B are expected to remain temporarily suspended for approximately 8–10 days. The Company is taking all necessary steps to restore operations at Unit-9B at the earliest.

A detailed investigation is currently in progress to determine the root cause of the incident and to identify appropriate corrective and preventive actions as may be considered necessary.

Additional details as per SEBI Circular no. SEBI/HO/CFD/CFD-PoD-1/P/CIR/2023/123 dated 13th July 2023, and SEBI Master Circular no. SEBI/HO/CFD/PoD2/CIR/P/2023/120 dated 11th November 2024, is mentioned in Annexure-A.

This is for your information and records.

Thanking you.

Yours faithfully,
for IOL Chemicals and Pharmaceuticals Limited

Abhay Raj Singh
Sr. Vice President & Company Secretary



Annexure A

Details as per SEBI Circular no. SEBI/HO/CFD/CFD-PoD-1/P/CIR/2023/123 dated 13th July 2023, and SEBI Master Circular no. SEBI/HO/CFD/PoD2/CIR/P/2023/120 dated 11th November 2024 is given below:

Particulars	Details
1. expected quantum of loss/damage caused;	There were no injuries to any employee or other personnel. The incident was promptly brought under control by the Company's site emergency response team in accordance with the established Onsite Emergency Management Plan. No material damage to plant, equipment or property has been observed.
2. whether loss/damage covered by insurance or not, including amount;	The Company's assets are adequately covered under its insurance policies. The extent of any insurable loss, if any, is being assessed and shall be dealt with in accordance with the applicable insurance coverage.
3. estimated impact on the production/operations in case of strikes/lock outs;	<p>The incident is confined to Unit-9B (Minoxidil Manufacturing Unit). Operations of Unit-9B are expected to remain temporarily affected for approximately 8–10 days.</p> <p>Other manufacturing units/plants remain unaffected and continue to operate normally. The overall impact on the Company's operations is not expected to be significant.</p>
4. factory/unit where the strike/lock out takes place including reasons for such strike	The fire incident occurred in Unit-9B (Minoxidil Manufacturing Unit) at the Company's manufacturing facility situated at Village Fatehgarh Channa, Mansa Road, Barnala – 148101, Punjab.